

# AX8052 ERRATA

## Errata Silicon Errata for AX8052

2015–December–10



ON Semiconductor®

[www.onsemi.com](http://www.onsemi.com)

### Introduction

This document lists silicon erratas, as well as features of the AX8052 that may be unexpected to the user.

This document refers to the silicon revisions listed in the table below.

Table 1.

Revision	SILICONREV Register
V1	0x8E
V1C	0x8F

### System Controller

#### *Wakeup from Deep Sleep on Falling Edge of PB3*

When in Deep Sleep mode, the Microcontroller is woken up from Deep Sleep by a falling edge on PB3. Care must be taken to avoid loosing wakeup events; that means hardware driving the PB3 pin must be designed to ensure generating a falling edge on PB3 while the microcontroller is in deep sleep.

Affected Revisions: V1

Fixed in Revision: V1C

#### *Setting RESET\_N Low Does Not Wake Up the Chip from Deep Sleep*

Workaround: For debugging, it is recommended to connect pin 7 of the Debug Adapter to PB3. The debug adapter will generate a falling edge when resetting the chip.

Chip-internal Power On Reset is not affected. Most applications therefore do not need to generate reset events on the RESET\_N pin and can leave the pin open; they are unaffected by this issue. Applications needing to reset the chip using the RESET\_N chip and requiring the use of the Deep Sleep mode are recommended to generate a falling edge on PB3 whenever RESET\_N is pulled low.

Affected Revisions: V1

Fixed in Revision: V1C

#### *RESET\_N Does Not Set GPIOENABLE to 1 after the Chip Once Entered Deep Sleep*

Once the chip entered (and exited) Deep Sleep, subsequent low pulses on RESET\_N will not set GPIOENABLE to 1. Therefore, GPIO Pins will not be enabled and continue to drive the value before reset.

Workaround: Set GPIOENABLE in software.

Affected Revisions: V1

Fixed in Revision: V1C

#### *Wakeup from Sleep Mode Resets System Controller Registers*

System Controller and GPIO register values correctly retained during sleep mode. When waking up from sleep mode, these registers are accidentally reset to their power-up default values, just before the CPU starts executing code from the reset vector address.

I/O pin signal levels are retained however, until the CPU writes one to GPIOENABLE after wakeup.

The main implications are that after Wakeup:

1. Wakeup timer is reset
2. PINCHGA, PINCHGB, PINCHGC may not be used to determine the wakeup cause
3. External crystal oscillators are stopped

Workaround:

1. Wakeup timer needs to be restarted after wakeup from sleep mode
2. External means must be used if it is desired to know which GPIO pin caused the wakeup
3. External crystal oscillators must be restarted after wakeup from sleep mode

Affected Revisions: V1

Fixed in Revision: V1C

#### *Clock Monitor Incorrectly Triggers Switch Back to FRCOSC*

The clock monitor incorrectly triggers switching back to FRCOSC. The clock monitor can therefore not be used reliably.

Workaround: Do not switch to a non-working clock. If there is any doubt a clock may be working before switching, software should check whether it works. This can be done using a general purpose timer. Two general purpose timers and an input capture unit may be used to easily measure the frequency ratio between any two clocks.

Affected Revisions: V1

Fixed in Revision: V1C

## AX8052 ERRATA

### *LPOSC Calibration Should Not Be Used*

The built-in automatic LPOSC calibration logic can cause LPOSC output glitches when enabled, and should therefore not be used.

Setting LPOSCKFILT to a value significantly lower than the maximum  $k_{\text{FILT}}$  value given in the programming manual (such as 100<sup>th</sup> of the maximum  $k_{\text{FILT}}$  value) will limit the frequency and the effect on the tuning word of the glitches. However, occasional glitches will still occur and propagate to the LPOSC consumers. The application must be able to tolerate the occasional LPOSC glitch (eg. if a timer is driven by LPOSC, it may occasionally increment twice per LPOSC period).

Workaround: Enable LPOSC calibration, but set LPOSCKFILT to zero. When an LPOSC Calibration interrupt is signaled (see register OSCCALIB), read the period register (LPOSCPER) and manually compute the new LPOSC tuning word. Delay writing the computed tuning word to LPOSCFREQ until approximately 1/4<sup>th</sup> of the LPOSC period after the LPOSC Calibration interrupt was signaled.

Affected Revisions: V1

Fixed in Revision: V1C

### *FRCOSC Calibration from Radio Clock*

If the Radio Clock is selected as calibration source for automatic FRCOSC calibration, calibration is only performed if the Radio Clock is also selected as system clock source (Register CLKCON), or the Radio Clock is selected as the source clock for one (or both) of the wake-up timer counters.

Affected Revisions: V1

Fixed in Revision: V1C

### *Changing Clock Sources May Accidentally Enable XOSC or LPXOSC*

Changing the clock source of any peripheral may accidentally enable the Crystal Oscillator or the Low Power Crystal Oscillator.

If crystals are connected to PA0/PA1 and PA3/PA4 and these pins are configured as analog inputs, the oscillators will switch off again after two falling clock cycles, and therefore this is not a problem.

Otherwise, these oscillators may be switched off again manually by calling libmf routines `turn_off_xosc()` and `turn_off_lpxosc()`. These routines require to toggle PA0/PA1 and PA3/PA4, respectively.

The accidental enabling of the Crystal Oscillators may be avoided by carefully switching clock sources as follows:

- System Clock (CLKCON)
  - ◆ Only switch to and from any clock source via FRCOSC
  - ◆ When switching from FRCOSC to LPXOSC, first switch to LPOSC, then to LPXOSC.  
When switching from LPXOSC to FRCOSC, first switch to LPOSC, then FRCOSC.

- Wakeup Timer (WTCFGA, WTCFGB)  
For setting WTCFGx to value y, use the following code sequence:
  1. WTCFGx |= 0x04;
  2. WTCFGx = 0x0F;
  3. WTCFGx &= y | 0xFC;
  4. WTCFGx = y;
- ADC (ADCCLSRC)  
Only switch ADC clock sources while all ADCCHxCONFIG registers are set to 0xFF
- SPI Master (SPSCKSRC)  
Only switch SPI Master clock sources while SPMODE is *not* set to SPI Master, i.e. SPMODE ≠ 01
- Timer (TxCLKSRC)  
Only switch Timer clock sources while TxMODE is set to Off, i.e. TxMODE = 000

Starting with revision V1C, the microcontroller features the MISCCTRL register, where both the Crystal Oscillator and the Low Power Crystal Oscillator may be disabled permanently.

Affected Revisions: V1

Fixed in Revision: V1C

### *Current Consumption after Entering Standby Mode*

Several Milliseconds to several hundred Milliseconds after entering sleep mode, device current consumption may briefly rise to approximately 2 mA and fall to normal levels again.

It is recommended to add seven NOP instructions immediately after the write instruction that sets PCON bits 1:0 to 01, or alternatively to use the libmf function `enter_sleep()` to prevent this current spike.

Affected Revisions: V1

Fixed in Revision: V1C

### *CPU Clock Rates Less than 10 kHz Not Recommended*

ON Semiconductor does not recommend to run the Microcontroller Core at less than 10 kHz (less than 10000 Instructions/s). Instead, the Microcontroller should be run from a faster clock source, and be put in standby or sleep mode when the system is idle.

Affected Revisions: V1

Fixed in Revision: V1C

## AX8052 ERRATA

### *Temperature Sensor Should Be Converted with the CPU in Standby Mode*

When converting the temperature sensor value, the CPU should be set to Standby mode. Otherwise, the converted temperature values will be noisier and the average will be affected as well. Wake-up from Standby mode can be effected either by an ADC interrupt handler, or using the code sequence below:

```
start conversion (see ADCCONV register)
for (;;) {
    EA = 0;
    if (ADCCONV & 0x80)
        break;

    EIE_6 = 1;
    enter_standby();
    EIE_6 = 0;
    EA = 1;
}
EA = 1;
read ADCCH0VAL0
read ADCCH0VAL1
```

The ADC clock source (register ADCCLKSRC) should be set to the same clock as the system clock (register CLKCON). The divider should be set so that the conversion rate falls into the range given by the datasheet. The ADC clock source should not be set to system clock (register ADCCLKSRC(2:0) should not be set to 110), because the system clock is turned off during standby. Most commonly, the microcontroller runs from the internal fast RC oscillator (CLKCON = 0x00), in this case the recommended ADC clock setting for temperature conversion is ADCCLKSRC = 0x30.

Affected Revisions: V1, V1C

### *Power-On Reset*

A power-up voltage ramp start voltage of 0.3 V or less is required for V1 silicon to reliably signal power-on Reset. For V1C, a start voltage of 0.6 V or less is required.

### *RESET\_N during VDDIO Ramp-Up*

If the external RESET\_N input is asserted (held low) during VDDIO Voltage Ramp-Up, an elevated current draw may be observed on VDDIO. As soon as RESET\_N is deasserted, the current returns to normal levels. Subsequent assertions of RESET\_N while VDDIO remains supplied will not cause any elevated current draw. This additional current will not damage the chip, it is however recommended to keep RESET\_N pulses short.

Affected Revisions: V1, V1C

### *Timer TxIRQRO, TxIRQRU, TxIRQEO, TxIRQEU Clear on Read takes Precedence over Set*

The timer status bits TxIRQRO, TxIRQRU, TxIRQEO, TxIRQEU are designed to clear on read. Clearing on read takes precedence in the affected chips. So software polling the status bits in a tight loop miss overflow or underflow events whenever the event coincides with reading the status register in the same clock cycle. It is recommended to use an interrupt handler on the affected chips to mitigate this issue.

Affected Revisions: V1, V1C

### *GPADC Missing Codes*

The GPADC converter exhibits missing codes at mid-level (or zero in differential mode) input.

Affected Revisions: V1, V1C

ON Semiconductor and the  are registered trademarks of Semiconductor Components Industries, LLC (SCILLC) or its subsidiaries in the United States and/or other countries. SCILLC owns the rights to a number of patents, trademarks, copyrights, trade secrets, and other intellectual property. A listing of SCILLC's product/patent coverage may be accessed at [www.onsemi.com/site/pdf/Patent-Marking.pdf](http://www.onsemi.com/site/pdf/Patent-Marking.pdf). SCILLC reserves the right to make changes without further notice to any products herein. SCILLC makes no warranty, representation or guarantee regarding the suitability of its products for any particular purpose, nor does SCILLC assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation special, consequential or incidental damages. "Typical" parameters which may be provided in SCILLC data sheets and/or specifications can and do vary in different applications and actual performance may vary over time. All operating parameters, including "Typicals" must be validated for each customer application by customer's technical experts. SCILLC does not convey any license under its patent rights nor the rights of others. SCILLC products are not designed, intended, or authorized for use as components in systems intended for surgical implant into the body, or other applications intended to support or sustain life, or for any other application in which the failure of the SCILLC product could create a situation where personal injury or death may occur. Should Buyer purchase or use SCILLC products for any such unintended or unauthorized application, Buyer shall indemnify and hold SCILLC and its officers, employees, subsidiaries, affiliates, and distributors harmless against all claims, costs, damages, and expenses, and reasonable attorney fees arising out of, directly or indirectly, any claim of personal injury or death associated with such unintended or unauthorized use, even if such claim alleges that SCILLC was negligent regarding the design or manufacture of the part. SCILLC is an Equal Opportunity/Affirmative Action Employer. This literature is subject to all applicable copyright laws and is not for resale in any manner.

## PUBLICATION ORDERING INFORMATION

### LITERATURE FULFILLMENT:

Literature Distribution Center for ON Semiconductor  
19521 E. 32nd Pkwy, Aurora, Colorado 80011 USA  
Phone: 303-675-2175 or 800-344-3860 Toll Free USA/Canada  
Fax: 303-675-2176 or 800-344-3867 Toll Free USA/Canada  
Email: [orderlit@onsemi.com](mailto:orderlit@onsemi.com)

**N. American Technical Support:** 800-282-9855 Toll Free  
USA/Canada  
**Europe, Middle East and Africa Technical Support:**  
Phone: 421 33 790 2910  
**Japan Customer Focus Center**  
Phone: 81-3-5817-1050

**ON Semiconductor Website:** [www.onsemi.com](http://www.onsemi.com)

**Order Literature:** <http://www.onsemi.com/orderlit>

For additional information, please contact your local Sales Representative